



Australian Fuel Injection

"We Deliver Service - Not Just Parts"

www.afi-australia.com.au

ECU REPAIRS - NOW AVAILABLE

Call 1300 000 234

Honda K24 Accord Euro and Odyssey 2003-2009, ECU Barometric Sensor Fault



POSSIBLE SYMPTOMS:

- Engine Light ON
- Engine rough idle/ hesitation
- Excessive fuel consumption
- Ant infestation (Yes its true, no joke)

Common code: P2229 Honda - Barometric Pressure (BARO) Sensor Circuit High Voltage

Yes, AFI Can Repair This Fault, Call Now!

Subaru Liberty, Tribeca, Outback 2003-2009, ECU Atmospheric Sensor Fault



POSSIBLE SYMPTOMS:

- Engine Light ON
- Engine rough idle/ hesitation
- Excessive fuel consumption

Common code: P2229 - Atmospheric Pressure Sensor Circuit High Voltage.



Australian Fuel Injection

"We Deliver Service - Not Just Parts"

www.afi-australia.com.au

Yes, AFI Can Repair This Fault, Call Now!

Mitsubishi Outlander, CG, CH, CJ Lancer 2005 - 2009 Throttle Body & Accelerator Pedal Sensor Fault



POSSIBLE SYMPTOMS:

- Throttle body and accelerator pedal sensor fault codes.
- Vehicle in limp mode, no acceleration

Common code: P2128 Throttle Pedal Position Sensor/Switch 'E' Circuit Input High & P2138 Accelerator Pedal Position Sensor Circuit Range/Performance

Yes, AFI Can Repair This Fault, Call Now!

VY-VZ BCM Indicator Problem



POSSIBLE SYMPTOMS:

Indicators staying on when locking doors with remote.

A common fault with the VZ Commodore is that the turn signal indicators will stay illuminated after the vehicle has been locked via the remote. This can result in a flat battery upon return to the vehicle as well as the melting of the plastic indicator housing/lens. The BCM module is located directly above the accelerator pedal.

Yes, AFI Can Repair This Fault, Call Now!



Australian Fuel Injection

"We Deliver Service - Not Just Parts"

www.afi-australia.com.au

VE Commodore/ Captiva Brake Lights Staying On



POSSIBLE SYMPTOMS:

- Brake lights staying on all the time.
- Misfire on acceleration,
- ABS codes.

Common Faults:: Brake light switch and faulty BCM.

Yes, AFI Can Repair This Fault, Call Now!

Vehicle: Nissan N16 Pulsar and A33 Maxima ECU idle control problems



Problem: ECU idle control problems

POSSIBLE SYMPTOMS:

- Low idle
- High idle
- Stalling
- Erratic idle

Common Faults:: P0505 Idle Control System Malfunction